

Should your DF-50 become contaminated, follow these steps to field clean and purge your fogger.

1. Remove cap and drain tank completely by turning unit upside down.
2. Fill tank with 1 liter of distilled water and shake vigorously. Drain tank.
3. Refill tank with 1 liter of distilled water and run unit for 10 to 15 minutes. Drain tank.
4. Run unit empty for 2 hours with fill cap off.
5. Refill unit with fresh Diffusion Fluid.
 - If unit continues to have low smoke out put or off colored fluid, contact your local distributor.